## **Test Results**

## ISO/FDIS 7176/19 30<sup>th</sup> August 2001

## Section 5.2 - Dynamic Performance Requirements

Wheelchair: Stowaway	RESULTS
Occupant: Hyb II 50 <sup>th</sup> %tile	NESOLIS
5.2.1 During the Test	
5.3.1 a). Horizontal ATD and wheelchair excursion limits as per limits shown in Table 3:-	4
Was the horizontal movement of the test wheelchair	YES
P- Point (X wc) less than 200 mm. (±5mm)	45mm
Was the horizontal movement of the dummy knee	YES
(X knee) less than 375 mm. (±5mm)	241mm
Was the horizontal movement of the dummy head	YES
(X head) less than 650 mm. (±5mm)	418mm
b). Was the ratio X knee/X wc >1.1	YES 5.3
c). Not Measured	
<ul> <li>d). Did the batteries of powered wheelchairs, or their surrogate parts:-</li> </ul>	N/A
i). move outside of the wheelchair footprint	N/A
ii). move into the wheelchair user's space	N/A
5.2.2 Post Test	
5.3.2 a). Did the wheelchair remain upright on the test platform Did the ATD remain in a seated posture in the test wheelchair with a torso angle less that 45°	YES
b). Did the wheelchair securement points show visible signs of material failure	NO
c). Did any components of a mass greater that 100g become detached from the wheelchair	NO
<ul> <li>d). Did any occupant contactable components fragment or separate with an edge of less than 2mm</li> </ul>	NO
<ul> <li>e). Did any primary load carrying components of the wheelchair show any visible signs of failure</li> </ul>	NO
<ul> <li>f). Did any 'tilt in space' locking mechanisms show signs of failure</li> </ul>	N/A
g). Was the ATD released without the use of tools	YES
f). Was the wheelchair released from the restraint system without the use of tools	YES
h). Was the average decrease of H-Point height relative to the wheelchair platform less than 20% of the pre-test height.	YES 12%
Has the wheelchair satisfied the Dynamic Test requirements of ISO/FDIS 7176/19 of 31/August/2003	YES